Annexure I (Para 1.6) Survey Questionnaire on Freight services in Indian Railways

	Date: GENERAL	Time:	Location:
1	Name of the siding:	_ Co	entact number:
	(i) Outward traffic (commodity):	From:	To:
	(ii) Inward Traffic (commodity)	From:	To:
	(iii) Rail Customer Since (month /year)		
	(iv) Average Annual Production /Total quanti	ty Handled (MTs):	
	(v) Average Annual Quantity handled throug	h Railways (MTs):	
	(Vi) Average Lead (Kms.):		

(VI) Average Lead (Kms.):	/								
ATTITUDE OF OFFICERS	/STAFF								
Does interaction with officers at D	ivisional /Zonal Headquarter meet with	adequate response?							
Always	Mostly	Some Times	Never						
Are Railway Staff at field level frie	ndly and responsive?								
Always	Mostly	Some Times	Never						
RELIABILITY/ TIMELINES	S OF FREIGHT SERVICES								
Is timely information made availab	ole in respect of availability of rake?								
Always	Mostly	Some Times	Never						
Are the rakes placed at the time p	referred by you?								
Always	Some Times	Never							
Are rakes supplied to you on time?									
Always	Mostly	Some Times	Never						
If you have been experiencing delays in placement of rakes, the average delay ranges									
Up to 5 hours	More than 5 hours but less than 12 hours	More than 12 hours but less than 24 hours	Beyond 24 hours						
Are the wagons supplied clean, fit	for loading and without damage?								
Always	Mostly	Some Times	Never						
Whether your rakes are moved wi	th in reasonable time after the completion	on of loading?							
Always	Mostly	Some Times	Never						
Do the rakes booked by you reach	n destination timely?								
Always	Mostly	Sometimes	Never						
What would make you offer more	traffic to Railways?								
Scheduled running of trains	Door to door service	Timely placement of rakes	Can't say						
What other changes would you suggest in freight operation of Railways that will make you offer major share of product to									
(i)									
	ATTITUDE OF OFFICERS Does interaction with officers at D Always Are Railway Staff at field level frie Always RELIABILITY/ TIMELINES: Is timely information made available Always Are the rakes placed at the time p Always Are rakes supplied to you on time Always If you have been experiencing del Up to 5 hours Are the wagons supplied clean, fit Always Whether your rakes are moved with the point of the rakes booked by you reach the point of the p	ATTITUDE OF OFFICERS /STAFF Does interaction with officers at Divisional /Zonal Headquarter meet with Always Mostly Are Railway Staff at field level friendly and responsive? Always Mostly RELIABILITY/ TIMELINESS OF FREIGHT SERVICES Is timely information made available in respect of availability of rake? Always Mostly Are the rakes placed at the time preferred by you? Always Mostly Are rakes supplied to you on time? Always Mostly If you have been experiencing delays in placement of rakes, the average Up to 5 hours More than 5 hours but less than 12 hours Are the wagons supplied clean, fit for loading and without damage? Always Mostly Whether your rakes are moved with in reasonable time after the completic Always Mostly Do the rakes booked by you reach destination timely? Always Mostly What would make you offer more traffic to Railways? Scheduled running of trains Door to door service What other changes would you suggest in freight operation of Railway Railways? (i)	ATTITUDE OF OFFICERS /STAFF Does interaction with officers at Divisional /Zonal Headquarter meet with adequate response? Always Mostly Some Times Are Railway Staff at field level friendly and responsive? Always Mostly Some Times RELIABILITY/ TIMELINESS OF FREIGHT SERVICES Is timely information made available in respect of availability of rake? Always Mostly Some Times Are the rakes placed at the time preferred by you? Always Mostly Some Times Are the rakes supplied to you on time? Always Mostly Some Times If you have been experiencing delays in placement of rakes, the average delay ranges Up to 5 hours More than 5 hours but less than 12 More than 12 hours but less than 24 hours Are the wagons supplied clean, fit for loading and without damage? Always Mostly Some Times Whether your rakes are moved with in reasonable time after the completion of loading? Always Mostly Some Times Othe rakes booked by you reach destination timely? Always Mostly Some Times Do the rakes booked by you reach destination timely? Always Mostly Some Times What would make you offer more traffic to Railways? Scheduled running of trains Door to door service Timely placement of rakes What other changes would you suggest in freight operation of Railways that will make you offer me Railways?						

Chapter 1 Freight Services in Indian Railways

13	Do you have access to FOIS for tracking the freight trains and ascertain its expected time of arrival?										
	Always	Mostly	Sometimes	Never							
14	If yes, is the information reliable?			_							
	Always	Mostly	sometimes	Never							
	TERMINALS AND SIDING	OPERATIONS									
15	Are adequate facilities such as ap	proach roads, lighting and stacking	area available?								
	YE	S	NO								
16	If not, the suggestions to improve	the service									
17	Are you satisfied with the working	hours at terminals?									
		YES	N	0							
18	Any suggestions regarding the wo	rking hours at terminals									
19	Are the mechanized loading /unloa	ading facility available at the termina	l?								
	YE	S	NO								
20	Do you feel that that the free time	allowed for loading /unloading adeq	uate?								
	Y	ES	No)							
21	Do the existing policies of Railway	s on investments for improving the	facilities at sidings offer adequa	te incentive?							
	Y	ES	N	0							
22	If not, what is your suggestion										
	SECURITY OF CARGO AN	D COMPENSATION									
23	Is adequate security arrangement	against pilferage and theft provided	for your cargo at terminal as we	ell as enroute?							
	Always	Mostly	Sometimes	Never							
24	Are the claims processing against	the damage /pilferage prompt and e	fficient?								
	Always	Mostly	Sometimes	Never							
	GRIEVANCE REDRESSAL										
25	Are you aware of the existing med	hanism for redressal of your grievar	ces?								
	Υ	ES	NO)							
26	Are your complaints with respect t	o freight operations handled prompt	y and effectively?								
	Always	Mostly	Sometimes	Never							

Annexure II (Para 1.7) SAMPLE SELECTION ON FREIGHT SERVICES

Zone	Division	Terminals selected	Interchange point selected	C&W depot selected
NEFR	Katihar Lumding	New Guwahati Jogighopa Bongaigaon refinery Numaligarh Oil Refinery	Katihar Malda Town	-
ER	Howrah Asansol	Durgapur Goods Shed Ultratech Cement Siding Asansol Goods Shed Barkeshwar Thermal Power Plant Siding Pakur Stone Quarry siding	Bhattanagar Asansol	Pakur Sitarampur
NR	Delhi Ambala	GNTP Bhatinda Ghaziabad Shakurbasti Jammu Tawi IFFCO, Aonla	Palwal Bhatinda Rewari Sriganganagar	Tuglakabad Ghaziabad Ambala Khanalampur
SR	Chennai Palghat	Dalmia Cement Siding Kudal Nagar Good shed Salem Market Goods Shed Panambur Goods Shed Kochi Refinery Siding Kurukkupet Goods Shed Tiruchirapalli Goods Shed	Renigunta Jollarpettai Kankanadi Thokkur	Tondiarpet Jollarpettai Kankanadi
SWR	Hubli Mysore	Ranjitpura JVSL, Tornagalu Tinaighat Sasalu New Mysore Good Terminal	Miraj Bellary Kankanadi	Hospet
NWR	Ajmer Jodhpur Bikaner	Jaisalmer Laxmi Cement Siding, Banas Kanakpura STPB-Birdhwal BNGS	Chittorgarh Palanpur Rewari Bandikuin	Madar Abu Road Jaisalmer Jodhpur Jaipur Lalgarh
ECR	Dhanbad Mughalsarai	Karpurigram Narayanpur Anant Raxaul Fatuha Patherdih Katrasgarh Jarangdish	MGS Up & Down yard Pradhankhunta Mahadiya	MGS Gaya Patherdih Barwadih
NER	Lucknow Izatnagar	Gonda Nakaha Jungle Rudrapur City	Persendi Katra Chamrua Farukkabad	Gonda Gorakhpur
SCR	Secunderabad Vijayawada	Rudram siding, Bhadrachalam Nagarjuna Fertiliser Corporation, Kakinada Port Rajsri Cement Siding, Malkheid Road Ultratech Cement Juturu KTPS, Kondapalli Sanat Nagar	Balharshah Wadi Duvvada Vijayawada	Ramagundam Sanat Nagar Kakinada Vijayawada
SECR	Bilaspur Raipur	Raigarh JSLK siding, Kirodimal Nagar Lafarge India Pvt.Ltd. Bijuri colliery MPSEB Siding Khaparkheda Century Cement, Tilda Ambuja Cement, Bhatapara	Jharsugda IB RVH	BCN Depot AKT P P Yard Bhilai Bhilai Marshalling yard

Chapter 1 Freight Services in Indian Railways

			oter 1 Freight Services in 1	
SER	Chakradharpur	Barajamada	Jharsugda	Bondamunda
	Kharagpur	Noamundi Roapway Sdg.	Joruli	TATA
		TISCO Sdg., TATÁ	Andal	Bokaro
	Adra	Bokaro Steel Plant siding (inward)	Asansol	Adra
	7 Kuru	Bokaro Steel Plant siding (outward)	risunsor	7 Kara
		Orissa Cement siding, Rajgangpur		
		Bhaga Goods Shed		
		JCP siding TATA		
		RSP Siding, Raurkela		
		Kolaghat TPP siding		
WCR	Jabalpur	Kota TP Station	Singrauli	New Katni Jn.
	•	Chambal Chemical & Fertilizer	Manikpur	Satna
	Kota	Maiher Cement	Swaimadhopur	KTT-Kota
	Rotu	JQSG	Chanderiya	Sakatpura
		Prism Cement	Chanderrya	Закагрига
TI/D	41 11 1		D.I.	0.1
WR	Ahmedabad	Mundra Port Siding	Palanpur	Sabarmati
		Kandla Port Good Shed		Vatva
	Vadodara	IFFCO Siding, Kandla		Karachiya
	Ratlam	Wanakbori TPS Sdg.		Vadodara Yard
		Vikram Cement Siding		
ECOR	Khurda	Cuttak,	Duvvada	Ore Exchange
		Jagdalpur	Bhadrak	yard/VSKP
	Waltair	Nayagarh,	Joruli	VSKP Steel Plant
	vv aitaii	Nergundi,	Jordin	Khurda Road, Paradeep
	C 1			Kilulua Koau, Faraueep
	Sambalpur	NTPC exchange yard TLHR		
		PPL/PRDP		
		VSKP siding		
		NALCO Siding, Damanjodi		
		Bhusan Power &Steel, Lapange		
NCR	Allahabad	Diamond Cement Siding, Parichha	Mughalsarai	Juhi
		IOC, Baad	Harduaganj	Baad
	Jhansi	NTPC, Dadri	Alwar	
		U.P Rajya Vidyut Nigam, Parichha,	Palwal	
	Agra Cantt.	Yamuna Bridge		
CR	Bhusawal	Nasik Thermal Power Station Siding	Jalgaon	Bhusawal
CK	Solapur		Manmad	
	<u> </u>	Orient Cement Siding		Daund
	Mumbai	MSEB Siding	Hotgi	Wadi
	Nagpur	Solapur Goods Shed	Wadi	Trombay
		Ghugas Coal Siding	Vasai Road	Igatpuri
		Wani Goods Shed	Roha	Ajni
		NTPG siding	Balharshah	Amla
		BRSG siding	Nagpur	
		Rajur Goods Shed I		
		Rajur Goods Shed II		
		Nasik Road terminal		
		BPCL siding, Trombay		
		Jalgaon Goods Shed		
		Cement siding, Wadi		
		Pune Goods Shed		
		BSC, Hotgi		
		Turbhe APM Complex		
		RCF siding, Thal-vaishet		
		MPBG siding, Sarni		
		New Mulund Goods shed		
		Umrer Coal siding		
		WCCL, Wani		

Annexure III (Para No. 3.7)

Statement showing the sample selection made for micro analysis of specific Issues in Corporate Safety Plan

Category	Issues	Extent of sample selection			
Zonal Hqrs	Safety related records of all concerned	100%			
	departments				
Divisional Hqrs	Safety related records of all concerned	Total 28 divisions on IR			
	departments				
Workshop	Safety related works (including POH, upgradation	18 workshops on IR			
	works etc.)				
Carriage sheds	Safety related works	17 sheds on IR			
Loco sheds	Safety related technological upgradation works	20 loco sheds on IR			
RDSO	Research projects & evaluation of new technology	100% of Safety related items			
ROH depots	Safety related technological upgradation works	15 Depots on IR			
Training Centres	Review of training modules and facilities provided	15 Training centres on IR			
	in respect of safety related training				
Works	Track Renewals etc.	A total of 271 works were			
		reviewed			
Production Units	Safety related technological upgradation works	100%			

Annexure-IV (Para 3.9.1.3)

Availability of Safety requirements at Manned/Unmanned Level Crossing Gates

Sl.No.	Details of items to be provided	SR	CR	ER	NR	WR	NWR	SCR	SER	NER	NCR	ECR	SECR	ECoR	SWR	WCR	NFR	Total
1	No. of LCs test checked	10	20	10	10	11	10	10	10	10	10	10	10	10	10	10	10	171
2	No. of LCs Manned	5	10	5	5	9	5	5	6	5	5	5	5	5	7	5	5	92
3	No. of LCs Provided with telephone	5	10	1	5	9	5	5	6	5	5	5	5	5	7	5	5	88
4	No. of LCs Interlocked	5	9	2	5	6	1	3	5	5	3	4	4	3	1	3	3	62
5	No. of LCs where wicket gates or stiles have been provided for pedestrians.	5	6	3	0	4	0	3	2	5	1	2	3	3	6	1	3	47
6	No. of LCs with reflectors provided on the stop disc on both sides of the gate.	4	9	5	5	6	5	4	6	5	5	4	2	5	7	4	4	80
7	No. of LCs with lamps provided on the gate on both sides for the road users	5	10	4	5	8	5	4	4	5	4	5	5	5	7	2	5	83
8	No. of LCs with speed breaker/bumps provided on either approach (unmanned level crossing only)	7	13	6	5	1	5	5	4	9	10	8	4	5	8	10	8	108
9	No. of LCs with warning boards for road users provided on both the approaches at the gate in the case of unmanned level crossings.	6	12	3	5	2	10	5	4	5	10	5	4	7	10	7	8	103
10	No. of LCs with locking arrangements provided for both gates.	5	10	5	5	9	5	5	6	5	5	5	3	5	7	5	5	90
11	No. of LCs with lifting barrier is less than 5 mtrs from centre of track	3	6	5	1	4	5	2	6	5	5	0	3	5	7	3	5	65

Annexure-V (Para 3.9.1.6 -C)

Vacancy position of Safety category staff as on 31.3.2008.

Zone	0]	perating De	pt.		vil Engg. De		y stan as on Me	echanical De	ept.	Electrical Dept.			
	Sanctioned strength	Vacancies	Percentage of vacancy	Sanctioned strength	Vacancies	Percentage of vacancy	Sanctioned strength	Vacancies	Percentage of vacancy	Sanctioned strength	Vacancies	Percentage of vacancy	
1	2	3	4	5	6	7	8	9	10	11	12	13	
SR	12059	992	8.23	17824	3967	22.26	4096	362	8.84	610	92	15.08	
CR	17355	1226	7.06	19445	2869	14.75	5380	396	7.36	613	161	26.26	
ER	14459	690	4.77	17190	5983	34.80	5725	614	10.72	777	154	19.82	
NR	21259	3532	16.61	26364	3441	13.05	7835	841	10.73	538	152	28.25	
WR	14547	1611	11.07	21543	1856	8.62	2018	419	20.76	636	105	16.51	
NWR	9276	917	9.88	12787	2885	22.56	1549	57	3.68	125	27	21.60	
SCR	14989	2278	15.20	21086	4296	20.37	2339	444	18.98	30	4	13.33	
SER	12832	1457	11.35	16773	4805	28.65	4616	728	15.77	227	49	21.59	
NER	7728	620	8.02	10495	1870	17.82	1205	69	5.73	82	17	20.73	
NCR	12183	1837	15.08	15401	1873	12.16	2776	169	6.09	1226	150	12.23	
ECR	14359	1944	13.54	19525	5596	28.66	4801	571	11.89	428	101	23.60	
SECR	9456	2021	21.37	11993	3403	28.37	1464	231	15.78	98	24	24.49	
ECoR	7231	1092	15.10	12081	4456	36.88	2339	519	22.19	239	52	21.76	
SWR	5886	1157	19.66	8399	3116	37.10	1893	376	19.86	116	43	37.07	
WCR	10086	806	7.99	15611	3139	20.11	2090	190	9.09	557	67	12.03	
NFR	8117	657	8.09	15882	2023	12.74	2681	338	12.61	208	66	31.73	
RPU/	343	46	13.41	17	1	5.88	0	0	0.00	805	52	6.46	
Metro													

Source: Safety CDO (Para 7.9 of CSP)

Annexure VI

(Para 3.9.1.6-E)

				s & Crew Lobbies	
Zone	Division	No. available	No.upgraded (out of Col.3)	No. under upgradation (Out of Col.3)	No. proposed for upgradation (Out of Col.3)
1	2	3	4	5	6
Running Roo					
SR	Chennai	10	2	2	0
	TVM	8	2	1	3
CR	Pune	4	4		0
	Bhusawal	6	6		0
	Nagpur Solapur	5	2	2 0	1 0
ED	SDAH	1	0	1	0
ER	HWH	1	1	0	0
	ASN	2	2	0	0
NR	LKO	10	0		9
1111	DLI	13	3		1
WR	Ratlam	4	3	0	1
****	Ahmedabad	12	4	1	2
NWR	BKN	5	5	0	0
	JU	3	2	1	0
SCR	SC	10	5	2	0
-	GTL	8	3	1	0
SER	Chakradharpur	10	1	4	0
	Kharagpur	5	1	0	1
NER		7	0	4	7
NCR	JHANSI	6	0	1	1
ECR	DHN	13	0	13	0
	MGS	4	3	1	0
SECR	Bilaspur	8	7	1	0
ECoR		4	2	1	1
SWR	Bangalore	8	4	2	0
WCR	Bhopal	8	5	1	0
NFR		9	0		0
RPU/Metro		0	0		0
Total		187	70	44	27
Crew Lobbie		_		.	
SR	Chennai	7	0	4	0
CD	TVM	4	1	1	2
CR	Mumbai	9	1	1	2
	Pune Bhusawal	5 7	<u>3</u> 7	0	0
	Nagpur	3	2	0	1
	Solapur				
ER			4	1	
	ISDAH	5	3	1	0
	SDAH ASN	9	3	2	2
	ASN	9	3 4	2 0	2 2
NR		9	3 4 2	2 0 0	2 2 0
NR	ASN HWH	9 6 2 9	3 4	2 0 0 2	2 2
	ASN HWH LKO DLI	9 6 2	3 4 2 5	2 0 0 0 2 2	2 2 0 2 1
NR WR	ASN HWH LKO DLI Ratlam	9 6 2 9 12	3 4 2 5 9	2 0 0 0 2 2	2 2 0 2 1
	ASN HWH LKO DLI	9 6 2 9 12 4	3 4 2 5 9	2 0 0 2 2 1	2 2 0 2 2 1
WR	ASN HWH LKO DLI Ratlam Ahmedabad	9 6 2 9 12 4	3 4 2 5 9 3 8	2 0 0 2 1 0 1	2 2 0 2 1 1 0 0
WR	ASN HWH LKO DLI Ratlam Ahmedabad BKN	9 6 2 9 12 4 9	3 4 2 5 9 3 8 1 1	2 0 0 2 1 0 1 4	2 2 0 2 1 0 0 0 1 1
WR NWR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU	9 6 2 9 12 4 9 6	3 4 2 5 9 3 8 1	2 0 0 2 1 0 1 4	2 2 0 2 1 0 0 0
WR NWR SCR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL	9 6 2 9 12 4 9 6 3	3 4 2 5 9 3 8 1 1 2 8 5	2 0 0 2 1 0 1 4 4 1 1	2 2 0 2 1 0 0 0 1 1 0 0 0
WR NWR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur	9 6 2 9 12 4 9 6 3 3 9 6	3 4 2 5 9 3 8 1 1 2 8 5	2 0 0 2 1 0 1 4 1 1 0 1 1 0	2 2 0 2 1 0 0 0 1 1 0 0 0 0 0 0
WR NWR SCR SER	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL	9 6 2 9 12 4 9 6 3 9 6 6	3 4 2 5 9 3 8 1 1 2 8 5 1 1	2 0 0 2 1 0 1 4 1 1 0 0 1 1 0	2 2 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur	9 6 2 9 12 4 9 6 3 3 9 6 6	3 4 2 5 9 3 8 8 1 2 2 8 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 2 1 0 1 4 1 1 0 0 1 1 0 0 1 1 0 0 1 1 0 0 0 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 0 2 1 1 0 0 0 1 1 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI	9 6 2 9 12 4 9 6 3 9 6 6	3 4 2 5 9 3 8 8 1 2 8 5 5 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 2 1 0 1 4 1 1 0 0 0 1 1 1 0 0 0 1 1 1 0 0 0 0	2 2 0 0 2 1 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN	9 6 2 9 12 4 9 6 3 3 9 6 6 6 3 3	3 4 2 5 9 3 8 1 2 8 8 5 1 1 1 1 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 0 2 1 0 1 4 1 1 0 0 1 1 0 0 3 1 1 0 0 1 1 0 0 0 1 1 0 0 0 1 1 0 0 0 1 0 0 0 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 0 2 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS	9 6 2 9 12 4 9 6 3 3 9 6 6 6	3 4 2 5 9 3 8 1 1 2 8 8 5 1 1 0 1 1 1 4 4 3 3 3 3 3 4 3 1 1 1 1 1 1 1 1	2 0 0 0 2 1 1 4 4 1 1 0 0 1 1 0 0 3 1 1 6 0 0 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 2 0 0 0 2 2 1 1 0 0 0 0 0 0 0 1 1 0 0 0 0
WR NWR SCR SER NER NCR ECR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN	9 6 2 9 12 4 9 6 3 3 9 6 6 6 3 3 4 3 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 4 2 5 9 3 8 1 1 2 8 8 5 1 1 0 1 1 4 3 3 5 5	2 0 0 0 2 1 1 4 1 1 0 0 1 1 0 0 3 1 1 0 0 3 1 1 0 0 0 0	2 2 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR SECR ECOR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS Bilaspur	9 6 2 9 12 4 9 6 3 3 9 6 6 6 3 3 10 4 4 3 6	3 4 2 5 9 3 8 8 1 2 2 8 5 5 1 1 0 0 1 4 4 3 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 2 1 1 0 1 4 1 1 0 0 1 1 0 0 3 3 1 6 0 0 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 0 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR SECR SECR SECR SWR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS Bilaspur Bangalore	9 6 2 9 12 4 9 6 3 9 6 6 6 6 3 3 9 4 4 3 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1	3 4 2 5 9 3 8 8 1 2 8 8 5 5 1 1 0 0 1 4 4 3 5 5 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 0 1 1 4 4 1 0 0 1 1 0 0 3 3 1 1 6 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 0 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR SECR ECoR SWR WCR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS Bilaspur	9 6 2 9 12 4 9 6 3 9 6 6 6 3 3 9 6 6 4 3 3 9 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 8 7 8	3 4 2 5 9 3 8 8 1 2 8 5 1 1 0 0 1 4 3 3 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 2 1 0 1 4 1 1 0 0 3 3 3 1 6 0 0 1 1 0 0 0 1 1 0 0 0 0 0 0 0 0 0	2 2 0 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR ECR SECR ECOR SWR WCR NFR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS Bilaspur Bangalore	9 6 2 9 12 4 9 6 3 9 6 6 6 6 3 3 9 4 4 3 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1	3 4 2 5 9 3 8 8 1 2 8 8 5 5 1 1 0 0 1 4 4 3 5 5 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 2 1 0 1 4 1 1 0 0 3 3 3 1 6 0 0 1 1 0 0 0 1 1 0 0 0 0 0 0 0 0 0	2 2 0 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR ECR SECR ECOR SWR WCR NFR RPU/	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS Bilaspur Bangalore	9 6 2 9 12 4 9 6 6 3 3 9 6 6 6 6 1 1 2 7 7 7 4 4 4 9 6 6 6 6 6 6 6 6 7 7 8 7 8 7 8 7 8 7 8 7	3 4 2 5 9 3 8 8 1 2 8 5 1 1 0 0 1 4 3 3 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 0 0 2 1 0 1 4 1 1 0 3 3 1 6 0 0 1 1 0 0 1 1 0 0 0 1 1 0 0 0 0 0	2 2 0 0 2 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0
WR NWR SCR SER NER NCR ECR ECOR SWR WCR NFR	ASN HWH LKO DLI Ratlam Ahmedabad BKN JU SC GTL Chakradharpur Kharagpur JHANSI DHN MGS Bilaspur Bangalore	9 6 2 9 12 4 9 6 3 9 6 6 6 3 3 9 6 6 4 3 3 9 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 8 7 8	3 4 2 5 9 3 8 8 1 2 8 8 5 1 1 0 1 4 3 3 5 5 1 2 6 6 7 1 1 1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	2 0 0 2 1 1 0 1 1 0 0 3 3 1 6 0 0 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

(Para 7.20, 7.21 of CSP)