Report of the Comptroller and Auditor General of India

for the year ended March 2014

Laid in Lok Sabha/Rajya Sabha on _____

Union Government (Railways)

No.24 of 2015 (Audit Report Volume II)

TABLE OF CONTENTS

Engineering-Open Line and Construction	Paragraph	Pages
PREFACE		iii
OVERVIEW		V
Chapter 1 – Review on 'Maintenance of Bridges in Indian Railways'		1-28
Introduction	1.1	2
Previous Audit Report	1.2	3
Audit objectives	1.3	3
Audit criteria	1.4	3
Audit scope, methodology and sample	1.5	4
Audit findings	1.6	4
Conclusion	1.7	27
Chapter 2 – Review on 'Procurement and Utilization of Track Machines in Indian Railways'		29-73
Introduction	2.1	21
Organizational structure	2.2	32
Audit objectives	2.3	32
Audit criteria	2.4	32
Audit scope and methodology	2.5	33
Audit findings	2.6	33
Conclusion	2.7	59
Appendix A to K		61-73
Chapter 3 – Review on 'Provision and utilization of Direction and General Charges provided in Works estimates of Construction Organization in Indian Railways'		74-106
Introduction	3.1	76
Audit objectives	3.2	77
Audit criteria	3.3	77
Audit scope and methodology	3.4	77
Sample size	3.5	78
Scope limitation	3.6	78
Audit findings	3.7	78

Conclusion	3.8	100
Appendix I & II		102-106
Chapter 4 – Review on 'Management of vacant land in Indian Railways'		107-125
Introduction	4.1	107
Audit objectives	4.2	108
Audit scope, methodology and sample	4.3	109
Organizational structure	4.4	109
Audit criteria	4.5	110
Audit findings	4.6	110
Conclusion	4.7	124
Chapter 5 – Paragraphs related to Engineering department of Indian Railways		126-147
Poor planning in construction of railway quarters led to avoidable extra expenditure including payment of leased accommodation	5.1	126
Unfruitful expenditure on construction of substructure of a Railway bridge	5.2	128
Infructuous expenditure in construction of new workshop	5.3	130
Commencement of a new line work without acquiring land for the project	5.4	132
Deficient planning for procurement of water led to unfruitful expenditure	5.6	133
Non-utilisation of Water recycling plants (WRPs) and consequent avoidable expenditure on water charges	5.6	136
Avoidable expenditure due to deficient planning and inefficient management of contract	5.7	138
Delay and Cost overrun due to award of contract without site clearance and improper planning	5.8	143
Infructuous expenditure on construction of rake handling platform	5.9	146
Annexure		147-175