

**Report of the
Comptroller and Auditor General of India**

Performance Audit

on

**Implementation of Deendayal Upadhyaya
Gram Jyoti Yojana (DDUGJY)/
Pradhan Mantri Sahaj Bijli Har Ghar Yojana
(SAUBHAGYA)**

Government of Karnataka
Report No. 5 of the year 2022

Table of contents

Paragraph No.	Contents	Page Number
	Preface	v
	Executive Summary	vi-x
Chapter – I		
	Introduction	1
1.1	Deendayal Upadhyaya Gram Jyoti Yojana	1
1.2	Pradhan Mantri Sahaj Bijli Har Ghar Yojana (SAUBHAGYA)	1-2
1.3	Cost sharing pattern	2
1.4	Organisation setup	2
1.5	Audit objectives	3
1.6	Audit criteria	3
1.7	Audit scope and methodology	3-4
1.8	Audit findings	4
1.9	Acknowledgement	4
Chapter II		
	Planning and Financial Management	5
	Planning	5
2.1	Field survey	5-7
2.2	Cost re-allocation in the DPRs	7-8
2.3	Preparation of DPRs under RGGVY	8-9
2.4	Statutory clearances	9
	Conclusion	9
	Recommendations	10
2.5	Financial Management	10-11
2.6	Fee fixed to PMA without inviting tenders	11-12
2.7	Additional expenditure on PMA	12-13
2.8	Extra expenditure on procurement of materials	13-14
2.9	Additional financial burden	14-16
2.10	Non-fulfilment of conditions for receipt of additional grant	16-17
2.11	Deduction of taxes	17-18
	Conclusion	18
	Recommendation	18

Paragraph No.	Contents	Page Number
Chapter III		
	Implementation of projects under the schemes	19
3.1	Status update	19-20
	Execution of projects under DDUGJY	20
3.2	Award of contracts in deviation from KTPP Act	20
3.3	Award and completion of projects	20-21
3.4	Works execution	21-22
3.5	Feeder segregation works	22-23
3.6	Metering	23
3.6.1	Non-completion of feeder metering led to opting out of the scheme	23-24
3.6.2	Metering of Distribution Transformers	24-25
3.7	Foregone energy savings	26
3.7.1	Due to deficient planning	26-27
3.7.2	Due to non-availability of breakers	27-28
3.8	Extension of contract	28-30
3.9	Quality Assurance Mechanism	30-31
3.10	Execution of works under SAUBHAGYA	31
3.10.1	Completion of works	31-32
3.10.2	Execution of works without sanctioned estimates	32-33
3.10.3	Discrepancies in material inspection at contractor's stores	33
3.10.4	Excess payment to contractor	33-34
3.11	Execution of works under RGGVY XII Plan	34
3.11.1	Deficiencies in execution	35
3.11.2	Electrification of BPL households at higher cost	36-37
3.11.3	Loss of subsidy due to non-completion of works	37-38
3.11.4	Shortage of materials and loss of subsidy	38-39
3.12	Execution of works under DDG	39
3.12.1	Award of contract to ineligible firm	39-41
3.12.2	Abnormal delay in electrification of households due to lack of forest clearance	41-42
3.12.3	Non-levy of liquidated damages for ₹ 69.90 lakh	42
	Conclusion	42
	Recommendations	43

Paragraph	Contents	Page Number	
Chapter IV			
	Survey findings and Monitoring issues	45	
4.1	Survey findings	45	
4.1.1	Beneficiary survey	45-46	
4.1.2	Village survey	46-47	
4.2 & 4.2.1	Violation of conditions of standard bid document	47-48	
4.2.2	Discrepancies in consumer service connections	48-49	
	Conclusion	49	
	Recommendation	49	
4.3	Monitoring issues	50	
4.3.1	Monitoring by various authorities	50-52	
	Conclusion	52	
	Recommendation	53	
Appendices		55	
No.	Contents	Paragraph	
1	Details of audit sampled projects under DDUGJY/SAUBHAGYA, RGGVY	1.7	55
2	Details of Grant and Expenditure under DDUGJY/SAUBHAGYA/RGGVY/DDG	2.5	56
3	Details of electrification of BPL Households under DDUGJY/SAUBHAGYA/RGGVY/DDG	2.5, 3.1	57
4	Details of tender premium paid on award of projects	3.2	58

Preface

1. This Report of the Comptroller and Auditor General of India has been prepared for submission to the Government for laying before the State Legislature of Karnataka under the provisions of Section 19A of the Comptroller and Auditor General's (Duties, Powers and Conditions of Service) Act, 1971.
2. The Report contains the results of Implementation of Deendayal Upadhyaya Gram Jyoti Yojana (DDUGJY)/Pradhan Mantri Sahaj Bijli Har Ghar Yojana (SAUBHAGYA) covering the period 2014-15 to 2020-21.
3. The audit was conducted in conformity with the Auditing Standards issued by the Comptroller and Auditor General of India.