



REPORT OF THE COMPTROLLER AND AUDITOR GENERAL OF INDIA

PERFORMANCE AUDIT OF MANAGEMENT OF STORM WATER IN BENGALURU URBAN AREA



GOVERNMENT OF KARNATAKA
REPORT NO. 2 OF THE YEAR 2021

**Report of the Comptroller and Auditor
General of India**

**Performance audit
of
Management of storm water in
Bengaluru Urban area**

Government of Karnataka
Report no. 2 of the year 2021

Table of contents

Paragraph	Contents	Page Number
	Preface	iii
	Executive Summary	v
Chapter I	Introduction	
1.1	Introduction	1
1.2	Geography of Bengaluru	1
1.3	Storm water drainage network in Bengaluru	1
1.4	River and lake network in Bengaluru	4
1.5	Rainfall and runoff yield in Bengaluru	5
1.6	Need for storm water management	7
1.7	Organisational structure for management of storm water drains in Bengaluru	8
Chapter II	Audit framework	
2.1	Audit objectives	9
2.2	Audit criteria	9
2.3	Audit scope and methodology	9
2.4	Joint study on geospatial data along with Regional Remote Sensing Centre, ISRO	10
2.5	Acknowledgement	11
2.6	Audit constraints	11
2.7	Previous audits	12
2.8	Organisation of audit findings	12
Chapter III	Collection and conservation of storm water	
3.1	Policies and regulatory framework	13
3.2	Coordination between different institutions	14
3.3	Storm water collection systems	15
3.4	Storm water conservation systems	26
3.5	Other factors affecting the conservation of storm water	29
Chapter IV	Planning, designing and construction of storm water drains	
4.1	Planning	33
4.2	Designing of roads and drains	49
4.3	Deficiencies in execution of projects involving remodelling of storm water drains	59

Chapter V	Protection and maintenance of storm water management systems	
5.1	Protection of storm water drains	73
5.2	Factors affecting/impeding connectivity/smooth flow of storm water in drains: Issues concerning maintenance of the SWD infrastructure	84
5.3	Monitoring and awareness	88
Chapter VI	Financial Management	
6.1	Allocation and expenditure towards management of SWDs	93
6.2	Deficiencies in preparation of annual budget proposals	94
6.3	Short provision of funds under 14 th Finance Commission	94
6.4	Continued maintenance of bank accounts for JnNURM	95
6.5	Non-reconciliation of statutory recoveries remitted to departments concerned	95
6.6	Weak financial control mechanism	96
	Appendices	99
	Glossary	120

List of Appendices

Appendix Number	Details	Page Number
1.1	Storm water drains as mapped in master plan of BBMP – Zone wise	99
2.1	Statement showing the gist of audit observations and recommendations of Committee on Local Bodies and PRIs pertaining to storm water drainage works executed under JnNURM (Para 4.1 of Report no. 6 of 2013, Government of Karnataka)	105
3.1	Status of compliance to NDMA Guidelines by the State Government/BBMP	106
3.2	List of disused lakes under BBMP	109
3.3	Typical changes (change in size and shape) noticed in lakes	110
3.4	Table showing a few lakes converted for other purposes	111
3.5	Results of verification of few drains in Vrishabhavathi valley	112
4.1	Statement showing the details of SWD works executed under Package 2 of Nagarothana Yojane	115
4.2	Statement showing the details of SWD works executed under Nagarothana Yojane	118
5.1	Instances of encroachments noticed during joint physical verification	119

Preface

1. This Report of the Comptroller and Auditor General of India has been prepared for submission to the Governor of Karnataka under CAG's DPC Act, 1971.

2. The Report covering the period 2013-18 contains the results of performance audit of 'Management of storm water in Bengaluru Urban area'.

3. Audit has been conducted in conformity with the Auditing Standards issued by the Comptroller and Auditor General of India.

